

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 32D0534781	(X3) Date Survey Completed 08/02/2022
Name of Provider or Supplier South Western Women's Options, Llc	Street Address, City, State 522 Lomas Blvd Ne, Albuquerque, NM	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The following standard deficiencies were cited as the results of a recertification survey on 08/02/2022. This facility was found NOT to be in compliance with the CLIA regulations found at 42 CFR for the specialties/subspecialties in which it was surveyed.
D2007	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>The samples must be examined or tested with the laboratory's regular patient workload by personnel who routinely perform the testing in the laboratory, using the laboratory's routine methods</p> <p>This STANDARD is not met as evidenced by: Based on the review of the 2020 - 2022 proficiency testing (PT) records, Personnel Report Form CMS-209, and interview with the technical consultant, the laboratory failed to ensure that the PT samples were rotated amongst testing personnel who routinely perform Rh (immunohematology) testing for 3 of 3 PT events in 2020, 3 of 3 PT events in 2021, and 1 of 1 PT event in 2022. Findings included: 1. Review of the 2020 - 2022 attestation forms for the American Proficiency Institute (API), revealed testing personnel - 2 (TP2) tested the proficiency samples for 3 of 3 PT events in 2020, and 3 of 3 PT events in 2021, and 1 of 1 PT event in 2022. 2. Review of the Personnel Report Form CMS-209 completed by the laboratory indicated a total of 13 testing personnel. 3. During interview on 08/02/2022 at 2:00 pm, the technical consultant confirmed the above findings.</p>