

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D0882284	(X3) Date Survey Completed 11/19/2024
Name of Provider or Supplier Murray Hill Urology, Pc	Street Address, City, State 120 East 34 Street, New York, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5417	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(d)</p> <p>Reagents, solutions, culture media, control materials, calibration materials, and other supplies must not be used when they have exceeded their expiration date, have deteriorated, or are of substandard quality.</p> <p>This STANDARD is not met as evidenced by: Based on direct observations, review of Quality Control (QC) and calibration data, as well as interview with the Laboratory Director (LD), Pathologist, and Testing Personnel (TP), the laboratory failed to remove from inventory expired reagents in the patient specimen processing laboratory. FINDINGS: 1. The surveyor's observations in the patient specimen processing laboratory confirmed on November 19, 2024, at approximately 11:30 A.M. that two boxes of HS CRP (high sensitivity C-reactive protein) lot: 36, expiration: October 31, 2024, were not removed from inventory. 2. The current, approved SOPs did not include instructions for removal of expired reagents and calibration materials from inventory. 3. The LD, Pathologist, and TP confirmed the findings on November 19, 2024, at approximately 11:30 A.M. It was noted that the LD, Pathologist, and TP confirmed the respective expired calibration and control materials were not utilized for patient specimen processing.</p>