

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  33D0999729	<b>(X3) Date Survey Completed</b>  08/09/2018
<b>Name of Provider or Supplier</b>  Prine Health Medical Group Pllc	<b>Street Address, City, State</b>  1129 Northern Boulevard, Suite 101, Manhasset, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6054</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on a surveyor's review of competency assessment records and confirmed in an interview with the technical consultant and the testing person, the laboratory director, acting as the technical consultant, failed to ensure that competency assessment for the three testing persons was performed in calendar year 2017.</p>