

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D1062061	(X3) Date Survey Completed 04/13/2026
Name of Provider or Supplier Advanced Hematology Oncology Pllc	Street Address, City, State 42-35 Main Street, Suite 3 H, Flushing, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2007	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>(b)(1) The samples must be examined or tested with the laboratory's regular patient workload by personnel who routinely perform the testing in the laboratory, using the laboratory's routine methods.</p> <p>This STANDARD is not met as evidenced by: Based on review of the American Proficiency Institute (API) Proficiency Testing (PT) records, Advanced Hematology Oncology, PLLC Standard Operating Procedures (SOPs), as well interview with the Laboratory Director (LD), the laboratory failed to test PT samples by personnel who routinely perform the testing in the laboratory. FINDINGS: 1. API PT reports 2024-1, 2024-2, 2024-3, 2025-1, 2025-2, and 2025-3 PT reports indicated only one Testing Person (TP) of three total TP performing PT. 2. The Advanced Hematology Oncology, PLLC SOP "Proficiency Testing" did not include instructions for rotating PT testing samples among the testing personnel who routinely perform patient testing. 3. The LD confirmed the findings by interview on April 13, 2026, at approximately 11:30 A.M.</p>