

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  33D1102811	<b>(X3) Date Survey Completed</b>  01/25/2018
<b>Name of Provider or Supplier</b>  Nshoa	<b>Street Address, City, State</b>  2632 East 14th Street Basement 3rd Floor, Brooklyn, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6128</b>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least annually after the first year, unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individual's performance must be reevaluated to include the use of the new test methodology or instrumentation.</p> <p>This STANDARD is not met as evidenced by: Based on the surveyor's review of personnel records and confirmed in an interview with the laboratory director and the clinical/technical consultant, the laboratory director (acting as the technical consultant) failed to evaluate the competency of the cytology technologist for the 2016 and 2017 calendar years.</p>