

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 36D1104050	(X3) Date Survey Completed 03/13/2018
Name of Provider or Supplier Accupath Diagnostic Laboratories Inc	Street Address, City, State 1737 Tennessee Avenue, Suite B, Cincinnati, OH	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6128	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least annually after the first year, unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individual's performance must be reevaluated to include the use of the new test methodology or instrumentation.</p> <p>This STANDARD is not met as evidenced by: Based on record review and an interview with the General Supervisor (GS), the Technical Supervisor (TS) failed to evaluate and document the 2017 competency of the GS who was responsible for high complexity Immunology testing. Findings Include: 1. Review of the laboratory's annual 2017 competency records found Testing Personnel completing competency assessing for the GS. 2. The GS confirmed the Testing Personnel had performed the annual competency assessment for the GS. The interview occurred on 03/13/2018 at 1:12 PM.</p>