

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 37D0469942	(X3) Date Survey Completed 02/05/2021
Name of Provider or Supplier Pathology Consultation Services Inc	Street Address, City, State 501 Alameda, Suite B, Norman, OK	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The recertification survey was performed on 02/05/2021. The findings were reviewed with the cytotechnologist general supervisor at the conclusion of the survey. The laboratory was found in compliance with a standard-level deficiency cited.
D5805	<p>TEST REPORT CFR(s): 493.1291(c)</p> <p>The test report must indicate the following: (c)(1) For positive patient identification, either the patient's name and identification number, or a unique patient identifier and identification number. (c)(2) The name and address of the laboratory location where the test was performed. (c)(3) The test report date. (c)(4) The test performed. (c)(5) Specimen source, when appropriate. (c)(6) The test result and, if applicable, the units of measurement or interpretation, or both. (c)(7) Any information regarding the condition and disposition of specimens that do not meet the laboratory's criteria for acceptability.</p> <p>This STANDARD is not met as evidenced by: Based on a review of records and interview with the cytotechnologist general supervisor, the laboratory failed to ensure patient test reports included the name and address of the laboratory location for 5 of 5 patient reports. Findings include: (1) On 02/05/2021, the surveyors reviewed 5 patient test reports and identified the reports did not accurately reflect the name and address where slide interpretations had been performed as follows: (a) Report #1 - A Pap smear slide interpretation was performed with the results reported on 11/03/2020: (i) The surveyors identified that the name and address of the microscopic examination on the report was "Norman Regional Hospital 901 N. Porter Norman OK 73071", which did not reflect where the test was performed; (ii) Surveyor #1 reviewed the report with the cytotechnologist general supervisor and asked the cytotechnologist general supervisor where the microscopic examination was performed. The cytotechnologist general supervisor stated on 02/05/2021 at 01:50 pm, the microscopic examination had been performed at Pathology</p>

Consultation Services 501 Alameda, Suite B, Norman OK 73071. (b) Report #2 - A Pap smear slide interpretation was performed with the results reported on 11/03/2020: (i) The surveyors identified that the name and address of the microscopic examination on the report was "Norman Regional Hospital 901 N. Porter Norman OK 73071", which did not reflect where the test was performed; (ii) Surveyor #1 reviewed the report with the cytotechnologist general supervisor and asked the cytotechnologist general supervisor where the microscopic examination was performed. The cytotechnologist general supervisor stated on 02/05/2021 at 01:51 pm, the microscopic examination had been performed at Pathology Consultation Services 501 Alameda, Suite B, Norman OK 73071. (c) Report #3 - A Pap smear slide interpretation was performed with the results reported on 11/03/2020: (i) The surveyors identified that the name and address of the microscopic examination on the report was "Norman Regional Hospital 901 N. Porter Norman OK 73071", which did not reflect where the test was performed; (ii) Surveyor #1 reviewed the report with the cytotechnologist general supervisor and asked the cytotechnologist general supervisor where the microscopic examination was performed. The cytotechnologist general supervisor stated on 02/05/2021 at 01:52 pm, the microscopic examination had been performed at Pathology Consultation Services 501 Alameda, Suite B, Norman OK 73071. (d) Report #4 - Histopathology grossing was performed with the results reported on 02/03/2021: (i) The surveyors identified that the name and address of the grossing on the report was "PATHOLOGY CONSULTATION SERVICES 501 Alameda, Suite B, NORMAN, OK 73071", which did not reflect where the test was performed; (ii) Surveyor #1 reviewed the report with the cytotechnologist general supervisor and asked the cytotechnologist general supervisor where the grossing was performed. The cytotechnologist general supervisor stated on 02/05/2021 at 01:53 pm, the grossing had been performed at Norman Regional Hospital 901 N. Porter, Norman, OK 73071. (e) Report #4 - Histopathology grossing and slide interpretation were performed with the results reported on 02/06/2021: (i) The surveyors identified that the name and address of the grossing and slide interpretation on the report was "PATHOLOGY CONSULTATION SERVICES 501 Alameda, Suite B, NORMAN, OK 73071", which did not reflect where the test was performed; (ii) Surveyor #1 reviewed the report with the cytotechnologist general supervisor and asked the cytotechnologist general supervisor where the grossing and slide interpretation were performed. The cytotechnologist general supervisor stated on 02/05/2021 at 01:55 pm, the grossing and slide interpretation had been performed at Norman Regional Laboratory Services Surgical Pathology 901 N. Porter; Box 1308, Norman, OK 73070-1308.