

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 37D1065302	(X3) Date Survey Completed 06/30/2021
Name of Provider or Supplier Weatherford Lab & X-Ray	Street Address, City, State 3733 Legacy Drive, Weatherford, OK	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The recertification survey was performed on 06/30/2021. The laboratory was found in compliance with a standard-level deficiency cited. The findings were reviewed with general supervisor #2 at the conclusion of the survey.
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on a review of records and interview with general supervisor #2, the laboratory failed to have a method to verify the accuracy of urine drug screen testing at least twice annually. Findings include: (1) On 06/30/2021 09:00 am, general supervisor #2 stated to the surveyor urine drug screen testing was performed using the MedTox Profile II ER test kit; (2) The surveyor reviewed proficiency testing records for 2019, 2020, and 2021. The laboratory had not enrolled and participated in a proficiency testing program for urine drug testing; (3) Since the laboratory was not enrolled in proficiency testing (participation in a proficiency testing program is not required for urine drug testing; it is not a regulated test), the surveyor asked general supervisor #2 if the laboratory had verified the testing for accuracy at least twice annually during 2019, 2020, and to date in 2021. General supervisor #2 provided the surveyor with documentation which showed the accuracy of the testing had not been verified between 05/2019 and 05/2020; (4) The surveyor reviewed the findings with general supervisor #2, who stated on 06/30/2021 at 10:50 am, the accuracy of the testing had not been verified at least twice annually as shown above.</p>