

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 38D0625696	(X3) Date Survey Completed 12/31/2018
Name of Provider or Supplier Downtown Salem Primary Care Lab	Street Address, City, State 1234 Commercial Street Se, Salem, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6109	<p>TECHNICAL SUPERVISOR QUALIFICATIONS CFR(s): 493.1449</p> <p>The laboratory must employ one or more individuals who are qualified by education and either training or experience to provide technical supervision for each of the specialties and subspecialties of service in which the laboratory performs high complexity tests or procedures. The director of a laboratory performing high complexity testing may function as the technical supervisor provided he or she meets the qualifications specified in this section.</p> <p>This STANDARD is not met as evidenced by: Based on review of records and discussion with the currently designated Technical Supervisor (TS) for Hematology, the TS does not qualify to act as a TS for high complexity (HC) Hematology testing. Findings include: 1. The current procedure for performing manual differentials on specimens for Hematology does not require smears with immature cells to be reviewed by a qualified individual or sent out to a facility that has said qualified staffing. 2. The current individual designated as a TS has only 2 of the 4 years of experience in Hematology required for a TS. 3. During an interview with the designated TS on 12/31/2018 at approximately 12:30 pm confirmed that she has only two of the four years required for a HC Hematology TS.</p>