

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  39D0657394	<b>(X3) Date Survey Completed</b>  02/16/2021
<b>Name of Provider or Supplier</b>  Lancaster Cancer Center Ltd	<b>Street Address, City, State</b>  703 Lampeter Rd, Lancaster, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on laboratory personnel interview and review of the laboratory Testing Personnel records on the date of the survey (02/16/2021), the Technical Consultant failed to assure the staff maintained competency for 2 of 2 testing personnel. Findings include: 1. Review of the laboratory Testing Personnel records revealed no platforms were stated in competency records for 2 of 2 Testing Personnel who performed Chemistry and Hematology tests from 08/16/2018 through the date of the survey. 2. The Laboratory Director acted as the Technical Consultant from 08/16/2018 to date of the survey. 3. During the survey at 11:00 pm, the senior Testing Personnel confirmed the above findings.</p>