

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  39D0710493	<b>(X3) Date Survey Completed</b>  07/25/2019
<b>Name of Provider or Supplier</b>  Harry J Hurley Md Pc Laboratory	<b>Street Address, City, State</b>  1101 Paoli Pk, West Chester, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5473</b>	<p>CONTROL PROCEDURES CFR(s): 493.1256(e)(2)(g)</p> <p>(e) For reagent, media, and supply checks, the laboratory must do the following: (e) (2) Each day of use (unless otherwise specified in this subpart), test staining materials for intended reactivity to ensure predictable staining characteristics. Control materials for both positive and negative reactivity must be included, as appropriate. (g) The laboratory must document all control procedures performed.</p> <p>This STANDARD is not met as evidenced by: Based on review of laboratory quality control records and interview with the Laboratory Director at the time of the survey (11:30 07/25/2019), the laboratory failed to document all quality control procedures performed, for histopathology slides read between 2018 and 2019. Findings include: 1. 13 patients had histopathology slides read on site between 04/02/2018 and 06/21/2019. 2. Review of the Laboratory stain log revealed no documentation of quality control for histopathology slides read between 2018 and 2019. 3. During the survey (12:15 07/25/2019), the Laboratory Director confirmed the above findings.</p>