

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D2109943	(X3) Date Survey Completed 10/11/2022
Name of Provider or Supplier Vascular Strategies Llc	Street Address, City, State 5110 Campus Drive, Suite 137, Plymouth Meeting, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6091	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(4)(iii)</p> <p>The laboratory director must ensure all proficiency testing reports received are reviewed by the appropriate staff to evaluate the laboratory's performance and to identify any problems that require corrective action.</p> <p>This STANDARD is not met as evidenced by: Based on the review of Vascular Strategies LLC proficiency testing (PT) results and interview with the Technical supervisor (TS) the laboratory failed to identify problems that required a corrective action for PT results for Folate Receptor Antibody Test (FRAT) Blocking Assay and FRAT Binding Assay in 2021. Findings Include: 1. On the day of survey, 10/11/2022 at 11:53 am, review of Vascular Strategies LLC PT revealed: - FRAT Binding Assay on 12/08/2021- score of 80%. - FRAT Blocking Assay on 12/08/2021- score of 80% 2. The laboratory director acknowledged the scores of 80% with their signature, but no assessment was made. 3. The TS confirmed the findings above on 10/11/2022 at 1:30 pm.</p>