

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  41D2144729	<b>(X3) Date Survey Completed</b>  06/07/2022
<b>Name of Provider or Supplier</b>  Csl Plasma, Inc	<b>Street Address, City, State</b>  66 Newport Ave, Rumford, RI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D2007</b>	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>The samples must be examined or tested with the laboratory's regular patient workload by personnel who routinely perform the testing in the laboratory, using the laboratory's routine methods</p> <p>This STANDARD is not met as evidenced by: Based on record review and staff interview, the laboratory failed to test proficiency testing (PT) samples in the same manner as routine patient samples by testing personnel (TP) who routinely perform the testing in the specialty of Chemistry. Findings include: 1. Record review on 6/01/2022 of the American Association of Bioanalysts (AAB) 2020 and 2021 Chemistry PT records revealed: a. 6 of 9 fully trained TP employed in 2020 did not participate in PT in 2020. b. 8 of 11 fully trained TP employed in 2021 did not participate in PT in 2021. 2. Record review of the laboratory's 2020 and 2021 PT tracking logs on 6/01/2022 confirmed the above findings. 3. Staff interview with the Center Manager on 6/01/2022 at 11:00 AM confirmed the above findings. 4. The laboratory performs 30,000 Chemistry tests annually.</p>