

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 42D0860669	(X3) Date Survey Completed 10/31/2019
Name of Provider or Supplier Mackey Family Practice Pa	Street Address, City, State 1025 W Meeting St, Lancaster, SC	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5221	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(d)</p> <p>All proficiency testing evaluation and verification activities must be documented.</p> <p>This STANDARD is not met as evidenced by: During an onsite recertification survey on 10/31/2019, based on proficiency testing records review, lack of documentation, and testing personnel interview, it was determined that the laboratory failed to evaluate and verify the accuracy of vaginal wet prep (VWP) assigned an unsatisfactory score for 2 of 6 proficiency testing events reviewed from 2018 and 2019 (2018, Event 2 and 2019, Event 1). Findings include: 1. Review of graded reports from American Proficiency Institute (API) revealed the following scores: a. 2018, Event 2: 0% for VWP b. 2019, Event 1: 0% for VWP 2. There was no corrective action documentation addressing these failures available for review on the day of the survey. 3. Testing personnel confirmed during an onsite interview on 10/31/2019 at 1:30 pm that the failures had not been evaluated.</p>