

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b> 42D2180396	<b>(X3) Date Survey Completed</b> 10/08/2025
<b>Name of Provider or Supplier</b> Riverview Family Medicine And Urgent Care	<b>Street Address, City, State</b> 2450 India Hook Road, Rock Hill, SC	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	An offsite Proficiency Testing Desk Review survey was conducted for Riverview Family Medicine and Urgent Care on October 8, 2025. The facility was found to be out of compliance with the conditions of 42 CFR Part 493, CLIA Laboratory Requirements. The following CONDITION LEVEL DEFICIENCIES were found to be out of compliance: D2016 - 42 C.F.R. 493.803 Condition: Successful participation [proficiency testing D6000 - 42 C.F.R. 493.1403 Condition: Laboratories performing moderate complexity testing; laboratory director
<b>D2016</b>	<p><b>SUCCESSFUL PARTICIPATION</b> CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: Based on a desk review of proficiency testing (PT) records from the Certification and</p>

	<p>Survey Provider Enhanced Reporting (CASPER) 0155 report and Wisconsin State Laboratory of Hygiene (WSLH) proficiency testing records, the laboratory failed to successfully participate in a proficiency testing program approved by HHS, for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. The laboratory failed to successfully participate in the specialty of Hematology for the analyte Red Blood Cells (RBC), Hematocrit (HCT), Hemoglobin (HGB), White Blood Cell Count (WBC), Mean Corpuscular Volume (MCV), Platelets (PLT). Refer D2130, D2131</p>
<p><b>D2130</b></p>	<p><b>HEMATOLOGY</b> CFR(s): 493.851(f)</p> <p>(f) Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.</p> <p>This STANDARD is not met as evidenced by: Based on a proficiency testing desk review of CASPER 0155 report and Wisconsin State Laboratory of Hygiene (WSLH) 2024 and 2025 proficiency testing records, the laboratory failed to achieve satisfactory performance (80% or greater) for the same analyte in two of three consecutive testing events in the subspecialty of Hematology for the analyte Red Blood Cells (RBC), Hematocrit (HCT), Hemoglobin (HGB), White Blood Cell Count (WBC), Mean Corpuscular Volume (MCV), Platelets (PLT). Findings included: 1. A review of the CASPER 0155 report revealed the following results: Hematology 2024-3rd Event the laboratory received unsatisfactory score of 0% for: Hematology Red Blood Cells (RBC) Hematocrit (HCT) Hemoglobin (HGB) White Blood Cells (WBC) Mean Corpuscular Volume (MCV) Platelets (PLT) Hematology 2025-2nd Event the laboratory received unsatisfactory score of 0% for: Hematology Red Blood Cells (RBC) Hematocrit (HCT) Hemoglobin (HGB) White Blood Cells (WBC) Mean Corpuscular Volume (MCV) Platelets (PLT) 2. A review of the Wisconsin State Laboratory of Hygiene (WSLH) proficiency testing records confirmed the laboratory received the above results.</p>
<p><b>D2131</b></p>	<p><b>HEMATOLOGY</b> CFR(s): 493.851(g)</p> <p>(g) Failure to achieve an overall testing event score of satisfactory performance for two consecutive testing events or two out of three consecutive testing events is unsuccessful performance.</p> <p>This STANDARD is not met as evidenced by: Based on a proficiency testing desk review of CASPER 0155 report and WSLH proficiency testing 2024 and 2025 records, the laboratory failed to achieve an overall satisfactory performance (80% or better) for the specialty of Hematology for two out of three consecutive testing events. Findings included: 1. A review of the CASPER 0155 report revealed the following results: Hematology 2024-3rd Event the laboratory received an unsatisfactory score of 0% for overall Hematology. Hematology 2025-2nd Event the laboratory received an unsatisfactory score of 0% for overall Hematology. 2. A review of the WSLH proficiency testing records confirmed the laboratory received the above results.</p>
<p><b>D6000</b></p>	<p><b>MODERATE COMPLEXITY LABORATORY DIRECTOR</b></p>

CFR(s): 493.1403

The laboratory must have a director who meets the qualification requirements of 493.1405 of this subpart and provides overall management and direction in accordance with 493.1407 of this subpart.

This CONDITION is not met as evidenced by:

Based on a proficiency testing desk review of CASPER 0155 report and Wisconsin State Laboratory of Hygiene (WSLH) 2024 and 2025 records, the laboratory director failed to provide overall management and direction of the laboratory services. The laboratory director failed to ensure proficiency testing samples were tested as required. Refer to D6016.

**D6016**

**LABORATORY DIRECTOR RESPONSIBILITIES**

CFR(s): 493.1407(e)(4)(i)

(e)(4)(i) The proficiency testing samples are tested as required under Subpart H of this part;

This STANDARD is not met as evidenced by:

Based on a proficiency testing desk review of CASPER 0155 report and Wisconsin State Laboratory of Hygiene (WSLH) 2024 and 2025 records, the laboratory director failed to ensure proficiency testing samples were tested as required. The laboratory director failed to ensure successful participation in an HHS approved proficiency testing program. Refer to D2130 and D2131.