

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D0028568	(X3) Date Survey Completed 10/10/2022
Name of Provider or Supplier Family Medical Clinic Of Harrogate, Pc	Street Address, City, State 170 Beech St, Suite 1, Harrogate, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2016	SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c) (a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history. This CONDITION is not met as evidenced by: ===== Hematology: The laboratory failed to maintain satisfactory participation in two consecutive events for the Red Blood Cell (RBC) analyte resulting in the initial unsuccessful proficiency testing (PT) occurrence for RBC (Refer to D2130) =====
D2130	HEMATOLOGY CFR(s): 493.851(f) Failure to achieve satisfactory performance for the same analyte in two consecutive

events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

===== Based on a desk review of the CMS CASPER Report 0155D and the laboratory's 2022 Proficiency Testing (PT) performance summary records from the American Proficiency Institute (API) Proficiency Testing program, the laboratory failed to maintain satisfactory performance for the Red Blood Cell (RBC) analyte in the 1st event 2022 and 2nd event 2022, resulting in the initial unsuccessful PT occurrence. The findings include: 1. A review of the CMS 0155D report revealed unsatisfactory RBC analyte scores of 60% for the 1st event of 2022 and 60% for the 2nd event of 2022. 2. A review of the laboratory's API Proficiency Testing records revealed unsatisfactory RBC analyte scores of 60% for the 1st event of 2022 and 60% for the 2nd event of 2022, resulting in the initial unsuccessful PT occurrence.

=====