

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  44D0307528	<b>(X3) Date Survey Completed</b>  09/11/2019
<b>Name of Provider or Supplier</b>  Urology Assoc Pc-Skyline Medical Ctr	<b>Street Address, City, State</b>  3443 Dickerson Rd, Suite 160, Nashville, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on review of employee personnel records for 2018-19 and interview with the Technical Consultant (TC) , the laboratory's technical consultant failed to document 4 of the six required criteria for assessing personnel competency. The findings include: 1) Review of employee personnel records for 2018-19 did not reveal documentation of 4 of the six required criteria of competency that include: direct observation of routine patient test performance; monitoring the recording and reporting of test results; review of intermediate test results or worksheets, and, assessment of problem solving skills. 2) An interview with the TC on September 11, 2019 at 12:30am confirmed testing person 1 of 3 evaluated during 2018 and 2019 were not evaluated using all of the six criteria for competency required by Centers for Medicare and Medicaid (CMS).</p>