

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  44D0308047	<b>(X3) Date Survey Completed</b>  11/28/2018
<b>Name of Provider or Supplier</b>  Laboratory For Kidney Pathology, Inc	<b>Street Address, City, State</b>  1916 Patterson Street Suite 501, Nashville, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D3011</b>	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on lab tour observations of reagent alcohol storage area, and interview with the laboratory supervisor, the laboratory failed to ensure protection from flammable hazards in 2017 &amp; 2018. The findings include: 1. Observation of the reagent Alcohol storage area determined the laboratory failed to ensure protection of flammable hazards for reagent alcohol in 2017 and 2018. 2. Interview with the laboratory supervisor on November 28th, 2018 at 12:30 pm confirmed the laboratory failed to ensure protection of flammable hazards for reagent alcohol in 2017 and 2018.</p>