

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D0965505	(X3) Date Survey Completed 11/14/2018
Name of Provider or Supplier Mercy Health Services, Inc	Street Address, City, State 143 Southeast Parkway Court, Franklin, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on review of testing personnel records and interview with the Laboratory Director, the Technical Consultant failed to assess the annual technical competencies for 4 out of 4 testing personnel (TP) in 2017 and 2018. The findings include: 1. Review of the testing personnel records for 4 out of 4 TP revealed the Technical Consultant failed to assess the annual technical competencies for 2017 and 2018. 2. Interview with the laboratory director on November 14, 2018 @ 12:30 pm confirmed the Technical consultant failed to assess the annual technical competencies for 2017 and 2018.</p>