

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  44D1036074	<b>(X3) Date Survey Completed</b>  08/25/2022
<b>Name of Provider or Supplier</b>  Hmg Sapling Grove Urgent Care	<b>Street Address, City, State</b>  350 Steeles Road, Unit 1, Bristol, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5311</b>	<p>SPECIMEN SUBMISSION, HANDLING, AND REFERRAL CFR(s): 493.1242(a)</p> <p>The laboratory must establish and follow written policies and procedures for each of the following, if applicable: (1) Patient preparation. (2) Specimen collection. (3) Specimen labeling, including patient name or unique patient identifier and, when appropriate, specimen source. (4) Specimen storage and preservation. (5) Conditions for specimen transportation. (6) Specimen processing. (7) Specimen acceptability and rejection. (8) Specimen referral.</p> <p>This STANDARD is not met as evidenced by: ===== Based on review of the laboratory's "Microbiology and Other Specimen Collection" policy, observation of the laboratory and interview with Testing Person #2, determined the laboratory failed to label Respiratory Tract specimens according to their policy. Findings include: 1. Laboratory's "Microbiology and Other Specimen Collection" policy states, "iii. Label wrapper with patient name and MRN or DOB." 2. Observation of respiratory tract specimens in the laboratory on August 25, 2022 at approximately 9:10 A.M. revealed specimens did not have MRN or DOB on wrapper. 3. Interview with Testing Person #2 in the laboratory on August 25, 2022 at approximately 9:10 A.M. confirmed the above findings. =====</p>