

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  44D1050198	<b>(X3) Date Survey Completed</b>  04/16/2021
<b>Name of Provider or Supplier</b>  Satellite Med, Llc	<b>Street Address, City, State</b>  1120 Sam'S Street, Cookeville, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6046</b>	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on review of the personnel records and interview with the Laboratory supervisor, determined the Technical Consultant failed to document competency assessments for five of five testing personnel for 2019 and 2020. The findings include: 1. Review of five of five testing personnel records, reveiled the Technical Consultant failed to perform Competency Assessments for 2019 and 2020. 2. Interview with the Laboratory Supervisor on April 16, 2021 at 9am confirmed the Technical Consultant failed to perform Competency Assessments for 2019 and 2020.</p>