

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D2076179	(X3) Date Survey Completed 03/19/2026
Name of Provider or Supplier Dyersburg Family Walk-In Clinic, Llc	Street Address, City, State 1954 St John Avenue, Dyersburg, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6005	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(c)</p> <p>(c) The laboratory director must: (c)(1) Be onsite at least once every 6 months, with at least 4 months between the minimum two on-site visits. Laboratory directors may elect to be on-site more frequently and must continue to be accessible to the laboratory to provide telephone or electronic consultation as needed; and (c)(2) Provide documentation of these visits, including evidence of performing activities that are part of the laboratory director responsibilities.</p> <p>This STANDARD is not met as evidenced by: Based on the lack of documentation and staff interview, the laboratory director failed to document onsite laboratory visits at least every six months in 2025. The findings include: 1. On the survey date, there was no documentation that the laboratory director performed onsite visits at least once every six months in 2025. 2. The technical consultant confirmed the findings during an interview on 3/19/2025 at 11:45 a.m.</p>