

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 45D0990052	(X3) Date Survey Completed 12/19/2025
Name of Provider or Supplier St Anthony Family Clinic	Street Address, City, State 680 Paredes Line Road, Brownsville, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	Based on a proficiency testing desk review survey performed on December 19, 2025, the laboratory was found to be out of compliance based on the following CONDITION LEVEL DEFICIENCIES: D2016 - 42 C.F.R. 493.803 Condition: Successful participation D6000 - 42 C.F.R. 493.1403 Condition: Laboratory Director, moderate complexity
D2016	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute's proficiency reports, the laboratory failed to achieve satisfactory</p>

	<p>performance in two of three testing events for the specialty of hematology (refer to D2131) and the analytes of red blood cell and hematocrit (refer to D2130) resulting in an initial unsuccessful performance.</p>
D2130	<p>HEMATOLOGY CFR(s): 493.851(f)</p> <p>(f) Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.</p> <p>This STANDARD is not met as evidenced by: Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute's proficiency reports, the laboratory failed to achieve satisfactory performance for two of three events in 2025 for the analytes of erythrocyte count and hematocrit. The findings included: 1. A review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile report, identified the laboratory received the following unsatisfactory performances for red blood cell count and hemoglobin in two of three events: a) red blood cel count 2025 API 1st event: 0% 2025 API 3rd event: 40% b) hematocrit 2025 API 1st event: 0% 2025 API 3rd event: 40% 2. A review of the American Proficiency Institute's proficiency reports from 2025 confirmed the proficiency testing scores.</p>
D2131	<p>HEMATOLOGY CFR(s): 493.851(g)</p> <p>(g) Failure to achieve an overall testing event score of satisfactory performance for two consecutive testing events or two out of three consecutive testing events is unsuccessful performance.</p> <p>This STANDARD is not met as evidenced by: Based on review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute's proficiency reports, the laboratory failed to achieve satisfactory performance for two of three events in 2025 for the specialty hematology. The findings included: 1. A review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile report, identified the laboratory received the following unsatisfactory performances for the specialty of hematology in two of three events: 2025 API 1st event: 0% 2025 API 3rd event: 78% 2. A review of the laboratory's American Proficiency Institute's proficiency testing results from 2025 confirmed the proficiency testing score.</p>
D6000	<p>MODERATE COMPLEXITY LABORATORY DIRECTOR CFR(s): 493.1403</p> <p>The laboratory must have a director who meets the qualification requirements of 493.1405 of this subpart and provides overall management and direction in accordance with 493.1407 of this subpart.</p> <p>This CONDITION is not met as evidenced by:</p>

Based on desk review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute's proficiency reports, the laboratory director failed to provide overall management and direction of the laboratory services. Refer to D6016.

D6016

LABORATORY DIRECTOR RESPONSIBILITIES

CFR(s): 493.1407(e)(4)(i)

(e)(4)(i) The proficiency testing samples are tested as required under Subpart H of this part;

This STANDARD is not met as evidenced by:
Based on desk review of the Certification and Survey Provider Enhanced Reporting (CASPER) Report 155 Individual Laboratory Profile and American Proficiency Institute's proficiency reports, the laboratory director failed to ensure successful participation in a HHS approved proficiency testing program for the specialty hematology (refer to D2131) and the analytes of red blood cell and hematocrit (refer to D2130) for two of three events in 2025, resulting in an initial unsuccessful performance.