

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 45D2057557	(X3) Date Survey Completed 05/08/2018
Name of Provider or Supplier Methodist Southlake Medical Center	Street Address, City, State 421 E State Highway 114-1st Floor, Southlake, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	<p>An unannounced onsite revisit was conducted 05/08/2018. This facility was found to remain NOT in compliance with the CLIA conditions for specialties/subspecialties surveyed for 42 CFR 493.1250 Analytic systems 493.1403 Moderate complexity laboratory director 493.1409 Technical consultant moderate complexity</p> <p>----- An entrance conference was held 09/11/2017 with the Technical Consultant, Testing Person #3, Quality/Risk Manager, and Director of Radiology. The survey process was discussed. An opportunity for questions and comments was given. Based upon the survey conducted 09/11/2017 through 09/14/2017, this facility was found to be NOT in compliance with the CLIA conditions for specialties/subspecialties surveyed for 42 CFR 493.803 Successful participation 493.807 Reinstatement of nonwaived laboratories 493.1250 Analytic systems 493.1403 Moderate complexity laboratory director 493.1409 Technical consultant moderate complexity 493.1421 Laboratory testing personnel 493.1487 Testing personnel An exit conference was held on 09/14/2017 with the Technical Consultant and Director of Radiology. The exit conference attendee was advised the laboratory was out of compliance and advised of conditions and deficiencies found during the survey. An opportunity for questions and comments was provided.</p>