

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 45D2112016	(X3) Date Survey Completed 08/09/2018
Name of Provider or Supplier Aeris Laboratory Llc	Street Address, City, State 100 W Nasa Parkway Suite 410b, Webster, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	<p>An unannounced revisit was performed on 8/9/18. The laboratory was found out of compliance with 1 Immediate jeopardy findings were abated. The laboratory voluntarily suspended testing on November in a letter from the laboratory director. No plans of corrections from the TX00248689 complaint inve The laboratory was found to be closed. No instrumentation or laboratory supplies were available for p interview with the director of operations on 8/9/18 at 1100 hours in the laboratory confirmed that no p since 11/18/16. The conditions not corrected were: D5300 - 42 C.F.R. 493.1240 Condition: PreAnaly F.R. 493.1250 Condition: Analytic Systems D6000 - 42 C.F.R. 493.1403 Condition: Laboratory Dir complexity D6033 - 42 C.F.R. 493.1409 Condition: Technical Consultant D6063 - 42 C.F.R. 493.14 Laboratories performing moderate complexity testing; testing personnel; D6076 - 42 C.F.R. 493.144 Director; high complexity D6108 - 42 C.F.R. 493.1447 Condition: Technical Supervisor D6168 - 42 Condition: Laboratories performing high complexity testing; testing personnel; Noted deficiencies an discussed with the laboratory representative at the exit conference. The facility representative was giv provide evidence of compliance with noted deficiencies and no such evidence was provided prior to s</p> <hr/> <p>25846 Complaint investigation TX00248689. The laboratory was found out of compliance with the C Immediate jeopardy findings were identified. The conditions not met were: D5300 - 42 C.F.R. 493.1 PreAnalytic Systems D5400 - 42 C.F.R. 493.1250 Condition: Analytic Systems D6000 - 42 C.F.R. 4 Laboratory Director; moderate complexity D6033 - 42 C.F.R. 493.1409 Condition: Technical Consu 493.1421 Condition: Laboratories performing moderate complexity testing; testing personnel; D6076 Condition: Laboratory Director; high complexity D6108 - 42 C.F.R. 493.1447 Condition: Technical R. 493.1487 Condition: Laboratories performing high complexity testing; testing personnel; Noted d correction were discussed with the laboratory representative at the exit conference. The facility repres opportunity to provide evidence of compliance with noted deficiencies and no such evidence was pro The laboratory voluntarily suspended testing on November 18, 2016 as documented in a letter from tl Note: The CMS-2567 (Statement of Deficiencies) is an official, legal document. All information mus for entering the plan of correction, correction dates, and the signature space. Any discrepancy in the c (s) will be reported to the Dallas Regional Office (RO) for referral to the Office of the Inspector Gene fraud. If information is inadvertently changed by the provider/supplier, the State Survey Agency (SA) immediately.</p>