

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  45D2213269	<b>(X3) Date Survey Completed</b>  06/27/2023
<b>Name of Provider or Supplier</b>  Jerry Lewis Md Pa Toxicology Laboratory	<b>Street Address, City, State</b>  6161 N State Hwy 161 #305, Irving, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D3011</b>	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: This is a NEW finding from previous initial survey. Based on observations, review of laboratory policies/procedures and confirmed in interview with facility personnel, the laboratory failed to ensure protection of testing personnel from biohazardous materials. Findings Included: 1. During a tour of the facility on 06/27/2023 at 01:20 p. m., the inspector observed a large stack of small biohazard bags piled in the facility hallway. 2. Review of laboratory policies/procedures revealed the laboratory failed to have a biohazard disposal policy. 3. During an interview on 06/27/2023 with Testing Person 2 (TP-2), TP-2 was asked when biohazard disposal was scheduled. TP-2 stated the facility was changing disposal companies and the last scheduled pickup was not completed. This confirmed the above findings.</p>