

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D0865203	(X3) Date Survey Completed 09/05/2024
Name of Provider or Supplier Cottontree Family Practice	Street Address, City, State 2230 N University Pkwy #1a, Provo, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on lack of documentation, and interview with Testing Personnel #1 (TP#1), the technical consultant failed to evaluate the competency of 1 of 1 employees performing serum pregnancy testing. The laboratory performs 10 serum pregnancy tests a year. Findings include: 1. Record review revealed the laboratory failed to document and perform competency assessment for 1 of 1 testing personnel performing serum pregnancy testing. 2. In an interview on 9/5/2024 at approximately 11:26 AM, TP#1 confirmed that the laboratory failed to document and perform competency assessment for 1 of 1 testing personnel performing serum pregnancy testing.</p>