

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  46D2086600	<b>(X3) Date Survey Completed</b>  10/12/2018
<b>Name of Provider or Supplier</b>  Revere Health Eagle Mountain Fm/Urgent Care	<b>Street Address, City, State</b>  4095 E Pony Express Parkway Suite 1, Eagle Mountain, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6054</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on testing personnel competency evaluations review, lack of documentation, and interview with staff, the laboratory technical consultant failed to evaluate testing personnel competency at least annually for 1 of 2 years reviewed for 3 of 9 testing personnel, (B, H, and I) performing non-waived testing . Findings include: 1. Personnel competency records reviewed failed to include documentation of annual personnel Complete Blood Cell Count competency for 2018 for testing person B (from 04/10/2017 to 10/12/2018), and for testing persons H (last one recorded on 08 /15/2016) and I (last recorded 04/03/2016) for 2017. 2. In an interview conducted on 10/12/2018 at approximately 12:00 Noon, the director confirmed competency was missed for some testing personnel in 2017.</p>