

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  46D2195540	<b>(X3) Date Survey Completed</b>  02/13/2023
<b>Name of Provider or Supplier</b>  Wasatch Behavioral Health	<b>Street Address, City, State</b>  151 South University Ave Suite 1200, Provo, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5401</b>	<p>PROCEDURE MANUAL CFR(s): 493.1251(a)</p> <p>A written procedures manual for all tests, assays, and examinations performed by the laboratory must be available to, and followed by, laboratory personnel. Textbooks may supplement but not replace the laboratory's written procedures for testing or examining specimens.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the laboratory's Standard Operating Procedures (SOP) manual and an interview with the Laboratory Director (LD), the laboratory failed to have a written procedure available for performing testing on the Siemens V-Twin System analyzer. The Siemens V-Twin System analyzer is used to perform approximately 98,330 chemistry tests annually. Findings include: 1. A review of the SOP manual at approximately 2:00 PM on 2/13/23 revealed that a procedure was not available for performing testing on the Siemens V-Twin System analyzer. 2. An interview with the LD at approximately 2:10 PM on 2/13/23 confirmed that the procedure manual did not contain a procedure for performing testing on the Siemens V-Twin System analyzer.</p>