

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D2270825	(X3) Date Survey Completed 01/22/2026
Name of Provider or Supplier Associates Of Pathology	Street Address, City, State 5475 South 500 East, Ogden, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6128	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>(b)(9) Thereafter, evaluations must be performed at least annually unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individuals performance must be reevaluated to include the use of the new test methodology or instrumentation.</p> <p>This STANDARD is not met as evidenced by: Based on personnel competency evaluations review, lack of documentation, and interview with the Technical Supervisor, the laboratory failed to reevaluate 2 of 3 testing personnel for the new BD COR Molecular instrument since 10/2024. The laboratory performs approximately 36,200 molecular tests annually. Findings include: 1. Competency and training records review revealed the laboratory failed to include documentation of performance reevaluation for 2 of 3 Testing Personnel for new high complexity molecular testing since 10/2024. 2. In an interview conducted on 1/22 /2026 at approximately 2:42 p.m., the Technical Supervisor confirmed the laboratory failed to include documentation of performance reevaluation for 2 of 3 Testing Personnel for new high complexity molecular testing since 10/2024.</p>