

<p><b>Statement of Deficiencies</b></p>	<p><b>(X1) Provider/Supplier/CLIA Identification Number</b></p> <p>49D0016288</p>	<p><b>(X3) Date Survey Completed</b></p> <p>02/16/2022</p>
<p><b>Name of Provider or Supplier</b></p> <p>Vpi And Student Health Services Laboratory</p>	<p><b>Street Address, City, State</b></p> <p>Mccomas Hall, Virginia Tech, 895 Washington St, Sw, Blacksburg, VA</p>	
<p>For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.</p>		

<p><b>(X4) ID Prefix Tag</b></p>	<p><b>Summary Statement of Deficiencies</b></p>
<p><b>D0000</b></p>	<p>An announced CLIA Recertification survey was conducted at the VPI Student Health Center, Schiffert Health Center on 02/14/22-2/16/22 by the Virginia Department of Health's Office of Licensure and Certification. The laboratory was surveyed under 42 CFR part 493 CLIA Requirements. The survey included on-site inspection of the main lab located at 895 Washington ST Blacksburg, VA and the molecular lab located at 4 Riverside Circle Roanoke, VA. Specific deficiencies cited are as follows: The laboratory is performing COVID-19 testing at both sites and is in compliance with the applicable COVID-19 reporting requirements.</p>
<p><b>D6120</b></p>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the Laboratory Personnel Report form (CMS 209), testing personnel (TP) files, and an interview, the technical supervisor (TS) failed to assess annual competency for one of six testing personnel the calendar year 2021 (main laboratory). Findings include: 1. Review of the CMS Form 209: Laboratory Personnel Report revealed that the laboratory director serves as the TS and there are six testing personnel in the laboratory. 2. Review of TP files revealed no competency assessment in 2021 for: Testing personnel A. (See Personnel Code Sheet.) 3. An exit interview with the general supervisor for the main laboratory at approximately 1600 on 2/14/22 confirmed the findings.</p>