

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 49D2022169	(X3) Date Survey Completed 01/14/2020
Name of Provider or Supplier Pariser Dermatology Specialists	Street Address, City, State 3907 Bridge Road, Suite 200, Suffolk, VA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at Pariser Dermatology Specialists, LTD on January 14, 2020 by the Virginia Department of Health's Office of Licensure and Certification. The laboratory was surveyed under 42 CFR part 493 CLIA Requirements. The specific deficiency cited is as follows:
D5433	<p>MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(b)(1)</p> <p>For equipment, instruments, or test systems developed in-house, commercially available and modified by the laboratory, or maintenance and function check protocols are not provided by the manufacturer, the laboratory must establish a maintenance protocol that ensures equipment, instrument, and test system performance that is necessary for accurate and reliable test results and test result reporting. The laboratory must perform and document the maintenance activities specified in paragraph (b)(1)(i) of this section.</p> <p>This STANDARD is not met as evidenced by: Based on a tour, review of maintenance logs, and interviews, the laboratory failed to establish maintenance protocols for the microscope utilized for histopathology patient testing during the twenty-two (22) months reviewed. Findings include: 1. During a facility tour at approximately 1:00 PM, the inspector noted the following microscope in the histopathology MOHS specimen processing area: Olympus Model BX43F Serial Number (SN) 7C50581 (labeled with a maintenance sticker that stated "service due January 2021"). The inspector noted the following microscope in the nurse station work areas: Accuscope Model 3004 SN 060235. 2. A review of the laboratory's equipment maintenance logs (timeframe: March 2018 to date of inspection) revealed no record of preventative maintenance for the Olympus Model BX43F SN 7C50581. The inspector requested to review the written maintenance protocols for the microscope utilized for histopathology patient testing listed above. No documentation was available for review. The laboratory manager stated, at approximately 3:00 PM,</p>

"We have protocols for Tidewater Medical Sales and Service to come in to perform yearly maintenance checks on the microscopes but our records indicate that they checked and PM'd only the Accuscope microscope that we use for wet prep exams. I will email our maintenance contact to make sure we have added the MOHS microscope to that annual PM protocol". The histotechnologist stated, at approximately 3:00 PM, "We had Tidewater Service come in last week to service the microscope in the MOHS lab but he did not leave any records". 3. In an exit interview with the practice manager and histotechnologist at approximately 3:30 PM, the above listed findings were confirmed.