

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 49D2093788	(X3) Date Survey Completed 01/29/2018
Name of Provider or Supplier Veracis, Inc	Street Address, City, State 737 N Fifth Street - Suite 304, Richmond, VA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA recertification survey was conducted at Veracis, Inc. on January 29, 2018 by the Virginia Department of Health's Office of Licensure and Certification. The laboratory was surveyed under 42 CFR part 493 CLIA Requirements. Specific deficiencies cited are as follows:
D6120	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a review of Laboratory Personnel Report form (CMS 209), testing personnel files, and an interview, the technical supervisor failed to assess annual competency for two (2) of four (4) testing personnel (TP) for 2017. Findings include: 1. Review of the CMS Form 209: Laboratory Personnel Report revealed that there are four (4) TP performing patient testing. 2. Review of personnel files revealed no competency assessments in 2017 for: Testing personnel A, Testing personnel D. (See Personnel Code Sheet.) 3. An interview with the technical supervisor and laboratory director at approximately 4:00 PM on January 29, 2018 confirmed that the technical supervisor failed to assess competency in 2017 for the TP listed above.</p>