

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 51D0993670	(X3) Date Survey Completed 11/24/2020
Name of Provider or Supplier Pineview Gynecology	Street Address, City, State 1322 Pineview Drive, Morgantown, WV	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced, on site, recertification survey was conducted at Pineview Gynecology on November 24, 2020, by the West Virginia Office of Laboratory Services. The laboratory was surveyed to assess compliance with the Federal Clinical Laboratory Improvement Amendment (CLIA) regulations under 42 CFR 493. Specific deficiencies are explained below.
D6064	<p>TESTING PERSONNEL QUALIFICATIONS CFR(s): 493.1423(a)</p> <p>Each individual performing moderate complexity testing must possess a current license issued by the State in which the laboratory is located, if such licensing is required.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the laboratory testing personnel (TP) files, the West Virginia licensure verification source, and an interview with the technical consultant (TC) and laboratory manager, 1 out of the 4 laboratory TP did not have a current West Virginia laboratory license as required by the West Virginia state rule WV 64 CFR 57 Clinical Laboratory Technician and Scientist Licensure and Certification Rule. Findings: 1. A comparative review of the laboratory TP files and the West Virginia licensure verification source identified one TP (TP1) with an expired West Virginia laboratory license. a. TP1 had a license that expired 1/1/2020. b. The 3 other TP had current West Virginia laboratory licenses. 2. During an interview with the TC and the laboratory manager, on 11/24/2020 at approximately 8:30 AM, both stated they had a current TP with an expired West Virginia laboratory license and they will immediately begin the process of reinstating TP1 license.</p>