

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 52D0393727	(X3) Date Survey Completed 08/21/2019
Name of Provider or Supplier Wildwood Family Clinic	Street Address, City, State 4901 Cottage Grove Rd, Madison, WI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2016	SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c) (a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history. This CONDITION is not met as evidenced by: Based on surveyor review of the federal Certification and Survey Provider Enhanced Reports (CASPER) Proficiency Testing (PT) and American Proficiency Institute (API) Proficiency Testing (PT) records, the laboratory failed to successfully participate in PT for the Cholesterol analyte in the Subspecialty of Routine Chemistry for events 2018-3 and 2019-2. See D2096.
D2096	ROUTINE CHEMISTRY CFR(s): 493.841(f)

Failure to achieve satisfactory performance for the same analyte or test in two consecutive testing events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

Based on surveyor review of the federal Certification and Survey Provider Enhanced Reports (CASPER) Proficiency Testing (PT) and American Proficiency Institute (API) PT records, the laboratory failed to have successful performance in PT for the Cholesterol analyte in the Subspecialty of Routine Chemistry for events 2018-3 and 2019-2. Findings include: 1. Review of PT records in the federal CASPER reporting system shows that the laboratory failed two out of three consecutive PT events for Cholesterol in the Subspecialty of Routine Chemistry - Event 2018-3, score 0% and Event 2019-2, score 20%. 2. Surveyor review of the API PT evaluation reports on August 21, 2019 confirmed the failed PT scores. This results in a failure to achieve an overall testing event score of satisfactory performance for two out of three consecutive testing events which is unsuccessful PT performance.