

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 52D1006777	(X3) Date Survey Completed 02/04/2021
Name of Provider or Supplier Aurora Medical Group D/B/A/ Aurora Health Center	Street Address, City, State 6609 W Greenfield Ave, West Allis, WI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on survey review of competency assessment records and interview with the technical consultant, the technical consultant's evaluation of competency was not specific to the Aurora Health Center-Six Points location for two of seven testing personnel in 2019 and 2020. Findings include: 1. Review of the competency assessment records for 2019 and 2020 showed no evaluation of competency specific to the Aurora Health Center-Six Points location for two of seven testing personnel. 2. Interview with the technical consultant on February 4, 2021 at 10:40 AM, confirmed the technical consultant did not evaluate competency specific to the Aurora Health Center-Six Points location for two of seven testing personnel in 2019 and 2020.</p>