

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 01D1084432	(X3) Date Survey Completed 06/27/2024
Name of Provider or Supplier Affinity Physician	Street Address, City, State 3686 Grandview Parkway, Suite 820, Birmingham, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6054	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on a review of Personnel records, a review of the Laboratory Personnel Report (CMS-209), and an interview with Testing Personnel #1, the Technical Consultant failed to perform and document competency assessment for Urine Sediment exams. This was noted for one of two competency assessment opportunities reviewed from the date of the last survey, 11/8/2022, to the date of the current survey, 6/27/2024. The findings include: 1. A review of Personnel records revealed Testing Personnel #1 to only have a completed competency assessment dated 6/3/2024. 2. A review of the CMS-209 confirmed Testing Personnel #1 was previously qualified since the last survey conducted on 11/8/2022. 3. During an interview 6/27/2024 at 10:30 AM, Testing Personnel #1 confirmed the absence of a 2023 competency assessment.</p>