

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 01D1089574	(X3) Date Survey Completed 03/02/2021
Name of Provider or Supplier Affinity Physicians Services	Street Address, City, State 5890 Valley Road Suite 200, Birmingham, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5407	<p>PROCEDURE MANUAL CFR(s): 493.1251(d)</p> <p>Procedures and changes in procedures must be approved, signed, and dated by the current laboratory director before use.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the Procedure Manual, the current Laboratory Director failed to approve the Policy and Procedure Manual once starting as Laboratory Director. The findings include: 1. A review of the Procedure Manual revealed that the former Laboratory Director signed the Policy and Procedure Manual 06/03/2020, 06/06/2019, and 05/08/2018. The current Laboratory Director started at the first of 2021. 2. A review of the Procedure Manual revealed in the Quality Assessment #6 Policies and Procedures - "...All procedures will be reviewed annually be the laboratory director or designee (Technical Consultant)."</p>