

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 01D2091573	(X3) Date Survey Completed 08/07/2025
Name of Provider or Supplier Southeast Clinical Laboratories	Street Address, City, State 3621 3rd Ave South, Birmingham, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the College of American Pathologists (CAP) proficiency test records and an interview with the Laboratory Director, the Laboratory failed to implement a mechanism to verify the accuracy of the viral markers Anti-HIV, Hepatitis (Anti-HBc), and Hepatitis (HBsAg). This was noted for one of thirty nine events reviewed in 2023. The findings include: 1. A review of the CAP proficiency records revealed the laboratory scored zero percent for Anti-HIV, Anti-HBc, and HBsAg on the 2023 VM-C Viral Marker proficiency test due to "failure to participate." 2. During an interview on 8/5/2025, at 10:13 AM, the Laboratory Director confirmed the above findings.</p>