

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 02D2054618	(X3) Date Survey Completed 09/13/2021
Name of Provider or Supplier Health North Family Medicine Llc	Street Address, City, State 2741 Debarr Rd Ste 302, Anchorage, AK	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2016	SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c) (a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history. This CONDITION is not met as evidenced by: Based on an off-site desk review of the laboratory's 2021 American Proficiency Institute (API) proficiency testing (PT) records and phone interview with the laboratory manager, the laboratory failed to successfully participate in PT. See D-tag 2130, unsatisfactory performance for the same analyte in two out of three consecutive hematology PT events. Refer to D2130.
D2130	HEMATOLOGY CFR(s): 493.851(f)

Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

Based on proficiency testing desk review, the laboratory's graded PT results from American Proficiency Institute (API), and phone interview with the laboratory manager, the laboratory failed to achieve satisfactory performance for the White Blood Cell Differential analyte in two out of three consecutive testing events.

Findings: 1. The laboratory is subscribed to the American Proficiency Institute for Hematology proficiency testing. 2. The laboratory received the following scores for White Blood Cell Differential: 2020 Third Testing Event = 0% 2021 Second Testing Event = 0%