

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D2140934	(X3) Date Survey Completed 01/04/2019
Name of Provider or Supplier Mesquite Gastroenterology	Street Address, City, State 7445 E Tanque Verde Rd, Tucson, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5413	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(b)</p> <p>The laboratory must define criteria for those conditions that are essential for proper storage of reagents and specimens, accurate and reliable test system operation, and test result reporting. The criteria must be consistent with the manufacturer's instructions, if provided. These conditions must be monitored and documented and, if applicable, include the following: (1) Water quality. (2) Temperature. (3) Humidity. (4) Protection of equipment and instruments from fluctuations and interruptions in electrical current that adversely affect patient test results and test reports.</p> <p>This STANDARD is not met as evidenced by: Based on lack of room temperature logs for review and interview with the facility personnel, the laboratory failed to document the temperature of the room where slide staining reagents are stored for testing under the sub-specialty of Histopathology . Findings include: 1. No room temperature logs pertaining to the room where staining reagents are stored were presented for review during the survey conducted on January 4, 2019. 2. The facility personnel confirmed that the laboratory was not documenting the room temperature as indicated above. 3. The test volume under the sub-specialty of Histopathology is approximately 4500 per year</p>