

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 04D2078963	(X3) Date Survey Completed 04/23/2026
Name of Provider or Supplier Baptist Eye And Surgery Center	Street Address, City, State 9800 Baptist Health Drive, Suite 660, Little Rock, AR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6032	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(14)</p> <p>(e)(14) Specify, in writing, the responsibilities and duties of each consultant and each person, engaged in the performance of the preanalytic, analytic, and postanalytic phases of testing, that identifies which examinations and procedures each individual is authorized to perform, whether supervision is required for specimen processing, test performance or results reporting, and whether consultant or director review is required prior to reporting patient test results.</p> <p>This STANDARD is not met as evidenced by: . Based upon review of personnel files for testing personnel listed on the form CMS-209, lack of documentation, and interviews with laboratory staff, the laboratory director failed to authorize two of seven testing personnel reviewed to perform testing without direct supervision. Survey findings include: A) Review of personnel files for seven testing personnel listed on form CMS-209 revealed written authorization from the laboratory director to perform moderately complex testing without direct supervision was not present for testing personnel (#'s 7 and 8 on the form CMS 209). B) In an interview, at 10:05 a.m. on 4/23/26 laboratory staff member #2 (as listed on the form CMS 209) confirmed the lack of written authorizations to perform tests for employees identified above.</p>