

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 05D0587665	(X3) Date Survey Completed 08/21/2019
Name of Provider or Supplier Urology Associates Of The Central Coast	Street Address, City, State 1310 Las Tablas Rd Ste 201, Templeton, CA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on review of the third quarter (Q3-2017) of the American Proficiency Institute (API) proficiency testing records and interview with the laboratory staff, it was determined that; the laboratory failed to at least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part. The findings included: a. Q3-2017, API received an unsatisfactory proficiency testing score of 50% for Urine sediment. b. Based on the laboratory's annual testing declaration submitted for 2017-2019, the laboratory analyzed and reported 398 urine sediments approximately during the time the laboratory received an unsatisfactory proficiency testing score. c. The laboratory staff confirmed (8/21 /2019, 1300) that the laboratory received the above unsatisfactory proficiency testing score.</p>