

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 05D0719950	(X3) Date Survey Completed 02/05/2020
Name of Provider or Supplier Associates In Urology	Street Address, City, State 3791 Katella Ave Ste 200, Los Alamitos, CA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6120	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the competency reporting, there was no evidence of a TP (testing personnel) competency reporting protocol in place. The findings include: a. The TS (technical supervisor) was asked to present a copy of the competency evaluations for 2018 and 2019 at 11:00 p.m. on 2/5/2020. b.The TS indicated there is not a MA (medical assistant) or CLS (clinical laboratory scientist) competency reporting protocol (neither a competency procedure nor documentation of a competency evaluation) in place. c. There were 7,500 tests performed in the laboratory in the last 12 months</p>