

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D0663269	<b>(X3) Date Survey Completed</b>  04/27/2022
<b>Name of Provider or Supplier</b>  Select Skin Md Llc	<b>Street Address, City, State</b>  1600 36th St Ste B, Vero Beach, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A recertification survey was conducted on April 27, 2022. Select Skin MD LLC clinical laboratory was not in compliance with 42 CFR 493, requirements for clinical laboratories.
<b>D5609</b>	<p><b>HISTOPATHOLOGY</b> CFR(s): 493.1273(e)(f)</p> <p>(e) The laboratory must use acceptable terminology of a recognized system of disease nomenclature in reporting results. (f) The laboratory must document all control procedures performed, as specified in this section.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the laboratory failed to document quality control information including the lot number, expiration date and open date for all reagents used in their Hematoxylin &amp; Eosin (H &amp; E) stains from 03/02/2021 to 04/27/2022. Findings: Review of the procedure titled Staining noted the laboratory used the following reagents in their H&amp;E stain: Reagent Alcohol, Hematoxylin Stain, Bluing Reagent, Eosin Stain, and Xylene Substitute. Review of the Stainer Maintenance log showed only the lot number of the Hematoxylin and Eosin Stain were recorded. On 04/27/2022 at 3:28 PM, the Lead Mohs Technician acknowledged that not all lot numbers, expiration dates and dates opened were documented.</p>