

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D0914874	(X3) Date Survey Completed 08/19/2020
Name of Provider or Supplier Oxford Biomedical Technologies Inc	Street Address, City, State 3555 Fiscal Court Ste 9, Riviera Beach, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced recertification survey was conducted on 8/19/20 at Oxford Biomedical Technologies, a clinical laboratory in Riviera Beach, Florida. The laboratory was not in compliance with 42 Code of Federal Regulations (CFR), Part 493, requirements for clinical laboratories.
D6128	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least annually after the first year, unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individual's performance must be reevaluated to include the use of the new test methodology or instrumentation.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with laboratory personnel, there was no documentation to indicate that the technical supervisor reviewed the performance of the general supervisor annually. The findings included: Review of personnel records on 8/19/20 revealed that there was no documentation of annual competency evaluations for the general supervisor for the past two years. During an interview with the general supervisor on 8/19/20 at 10:45 a.m., he confirmed that he had not had an evaluation over the past two years.</p>