

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D0992170	<b>(X3) Date Survey Completed</b>  10/16/2019
<b>Name of Provider or Supplier</b>  Group M Dermatology Pa D/B/A	<b>Street Address, City, State</b>  2101 Us Hwy 1, Jupiter, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	An announced recertification survey was conducted on 10/16/19 at Group M Dermatology Pa dba Jupiter Dermatology & Hair Restoration, a clinical laboratory in Jupiter, Florida. Group M Dermatology Pa dba Jupiter Dermatology & Hair Restoration is not in compliance with Code of Federal Regulations (CFR) 42, Part 493, Laboratory Requirements.
<b>D6054</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with laboratory personnel, the technical consultant did not document performance evaluations for two of three testing personnel. The findings included: Review of personnel records for the past two years revealed that there were quarterly competency evaluations for the histotechnician, but not for the two physician's assistants that performed potassium hydroxide (KOH) preps. During an interview with the Office Manager on 10/16/19 at 10:40 a.m., she confirmed they had not been documenting evaluations of the physician's assistants.</p>