

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1036214	(X3) Date Survey Completed 12/09/2022
Name of Provider or Supplier Brian G Fabian Md Pa	Street Address, City, State 7560 Winkler Rd, Fort Myers, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced recertification survey was conducted 12/6/22 through 12/9/22 at Brian G Fabian MD PA, a clinical laboratory in Fort Myers, Florida. Brian G Fabian MD PA is not in compliance with Code of Federal Regulations (CFR) 42, Part 493, Laboratory Requirements. The following is description of the Standard-level deficiency.
D5805	<p>TEST REPORT CFR(s): 493.1291(c)</p> <p>The test report must indicate the following: (c)(1) For positive patient identification, either the patient's name and identification number, or a unique patient identifier and identification number. (c)(2) The name and address of the laboratory location where the test was performed. (c)(3) The test report date. (c)(4) The test performed. (c)(5) Specimen source, when appropriate. (c)(6) The test result and, if applicable, the units of measurement or interpretation, or both. (c)(7) Any information regarding the condition and disposition of specimens that do not meet the laboratory's criteria for acceptability.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with the office manager, the laboratory failed to have the correct address of the laboratory location where the histopathology testing was performed for 4 out of 4 reports reviewed. The findings included: Review of patient reports for Patient specimen identification numbers 849, 853, 862, and 864 revealed none of the reports included the address where the testing was performed. On 12/6/22 at 2:35 p.m., the Office Manager said the address on the patient reports for 2 out of 2 years (2020 - 2022) was the practice's other location. The Office Manager said they did not know that the address on the report needed to be the address where the histopathology testing was performed.</p>