

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1042584	(X3) Date Survey Completed 02/12/2019
Name of Provider or Supplier Bradley P Grant Md Pa	Street Address, City, State 1480 S Wickham Rd, West Melbourne, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5413	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(b)</p> <p>The laboratory must define criteria for those conditions that are essential for proper storage of reagents and specimens, accurate and reliable test system operation, and test result reporting. The criteria must be consistent with the manufacturer's instructions, if provided. These conditions must be monitored and documented and, if applicable, include the following: (1) Water quality. (2) Temperature. (3) Humidity. (4) Protection of equipment and instruments from fluctuations and interruptions in electrical current that adversely affect patient test results and test reports.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the laboratory failed to record the humidity of the room where testing was performed from 2/12/17 to 2/12/19. Findings: The manual for the Leica CM1510S cryostat noted that the relative humidity of the laboratory should be a "relative humidity max. 60%." A review of the laboratory's logs showed that the laboratory failed to record the humidity of the room where testing was performed On 2/12/19 at 2:25 PM, Histotechnologist/Mohs Technician acknowledged that they did not record the humidity of the laboratory.</p>