

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1042584	(X3) Date Survey Completed 01/19/2021
Name of Provider or Supplier Bradley P Grant Md Pa	Street Address, City, State 1480 S Wickham Rd, West Melbourne, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A recertification survey was conducted on January 19, 2021. Bradley P Grant MD PA clinical laboratory was not in compliance with 42 CFR 493, requirements for clinical laboratories.
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on record review and staff interview, the laboratory failed to verify the accuracy of the reading and interpretation of the Hematoxylin and Eosin (H&E) stain at least twice annually in 2019. Findings: The laboratory used peer review to verify the accuracy of the reading and interpretation H&E stains. Review of the laboratory's records showed that peer review for the Laboratory Director was only done once during 2019, on 2/11/19. During an interview on 1/19/21 at 2:41 PM, the Mohs Technician acknowledged that peer review was performed only once during 2019.</p>